

BASIC
AIR CONTAMINANT DISCHARGE PERMIT

Lane Regional Air Protection Agency
1010 Main Street
Springfield, OR 97477
(541) 736-1056

This permit is being issued in accordance with the provisions of LRAPA's Rules and Regulations and based on the land use compatibility findings included in the permit record.

ISSUED TO:

Turtle Mountain, LLC
P. O. Box 21938
Eugene, OR 97402

INFORMATION RELIED UPON:

Application No.: 56169
Date Received: March 7, 2011

PLANT SITE LOCATION:

4660 Main St. Bldg. C Suite 460
Springfield, OR 97478

LAND USE COMPATABILITY STATEMENT:

Approving Authority: City of Springfield
Approval Date: March 8, 2011

ISSUED BY THE LANE REGIONAL AIR PROTECTION AGENCY



Merlyn L. Hough, Director

MAR 11 2011

Dated

Source(s) Permitted to Discharge Air Contaminants (LRAPA Title 37, Section 37-0020):

Table 1 Code	Source Description	SIC
Part A, 8	Sources not elsewhere classified with actual emissions of more than 1 ton/year VOC and/or HAP.	2024

1.0 STATEMENT OF PURPOSE

- 1.1 Permitted Activities** The permittee is allowed to discharge air contaminants from processes and activities related to the air contaminant source(s) listed on the first page of this permit until this permit expires, is modified, revoked or rescinded as long as the permittee complies with the conditions of this permit.

2.0 GENERAL EMISSION STANDARDS AND LIMITS

- 2.1 Production limits** The permittee is prohibited from processing 20,000 or more tons of desiccated coconut per year without first notifying the agency.
- 2.2 Visible emission limits** Emissions from any air contaminant source must not exceed an opacity equal to or greater than 20% for a period aggregating more than 3 minutes in any one hour. "Opacity" means the degree to which an emission reduces transmission of light and obscures the view of an object in the background.
- 2.3 Fugitive Emissions** The permittee must take reasonable precautions for preventing fugitive dust emissions.
- a. Treating vehicular traffic areas of the plant site under the control of the permittee;
 - b. Operating all contaminant-generating processes so that fugitive-type dust associated with the operation will be adequately controlled at all times;
 - c. Storing collected materials from air pollution control equipment in a covered container or other method equally effective in preventing the material from becoming airborne during storage and transfer.
- 2.4 Particulate Matter Fallout** The permittee must not cause or permit the emission of any particulate matter larger than 250 microns in size at sufficient duration or quantity, as to create an observable deposition upon the real property of another person. LRAPA will verify that the deposition exists and will notify the permittee that the deposition must be controlled.
- 2.5 Nuisance and Odors** The permittee must not cause or allow air contaminants from any source to cause a nuisance. Nuisance conditions will be verified by LRAPA personnel.

- 2.6 Other Regulations** In addition to the specific requirements listed in this permit, the permittee must comply with all other legal requirements enforceable by LRAPA.

RECORDKEEPING AND REPORTING REQUIREMENTS

- 2.7 Records** The permittee must maintain all records pertaining to pollutant emissions (e.g., plant production data) for at least 2 years from the date of the record.
- 2.8 Permit Renewal** An application to renew the permit is due 60 days prior to the permit expiration date.
- 2.9 Construction or Modification Notices** The permittee must notify LRAPA before adding new or modifying existing equipment to the extent that process equipment is substantially changed or added to, or emissions are significantly changed or increased.
- 2.10 Notice of Change of Ownership or Company Name** The permittee must promptly notify LRAPA of any change of mailing address, company name, or plant ownership. The permit will expire 60 days after a change in the legal entity owning/operating the facility unless application, with appropriate fees, is made to transfer the permit to the new entity.
- 2.11 Where to Send Reports and Notices** The reports and notices, with the permit number prominently displayed, must be sent to the LRAPA office identified on the cover page of the permit.

3.0 FEES

- 3.1 Fees** The Annual Fee specified in LRAPA Title 37, Section 37-0020, Table 2, Part 2 for a Basic ACDP is due on **December 1** of each year this permit is in effect. An invoice indicating the amount, as determined by LRAPA regulations, will be mailed prior to the above date.

4.0 GENERAL CONDITIONS

- 4.1 Masking of Emissions** The permittee must not cause or permit the installation of any device or use any means designed to mask the emissions of an air contaminant that causes or is likely to cause detriment to health, safety, or welfare of any person or otherwise violate any other regulation or requirement.

- 4.2 Open Burning** The permittee may not conduct any open burning except when approved by LRAPA in advance.
- 4.3 Asbestos** All activities involving asbestos-containing materials, including, but not limit to, demolition, renovation, repair, construction, and maintenance must be performed by persons certified for asbestos abatement projects. Accumulation of asbestos containing material is prohibited.
- 4.4 Permit Availability** The permittee must have a copy of the permit available at all times.
- 4.5 LRAPA Inspections** The permittee must allow LRAPA's representatives access to the plant site and pertinent records at all reasonable times for the purposes of performing inspections, surveys, collecting samples, obtaining data, reviewing and copying air contaminant emissions discharge records and conducting all necessary functions related to this permit.
- 4.6 Legal Disclaimers** The issuance of this permit does not convey any property rights in either real or personal property, or any exclusive privileges, nor does it authorize any injury to private property or any invasion of personal rights, nor any infringement of federal, state, or local laws or regulations.
- 4.7 Permit Revocation** This permit is subject to revocation for cause.
- 4.8 LRAPA Contact** Call the LRAPA office in Springfield at (541) 736-1056.

Lane Regional Air Protection Agency

**BASIC
 AIR CONTAMINANT DISCHARGE PERMIT
 REVIEW REPORT**

Turtle Mountain, LLC
 4660 Main St. Bldg. C Suite 460
 Springfield, OR 97478

Reports			NSPS	NESHAP	Public Notice
Annual	Semi-annual	Excess Emissions			
N/A	N/A	X	N/A	N/A	1

1. The proposed permit is a new permit for an existing source.
2. The permittee operates a coconut non-dairy ice cream base processing facility.
3. This facility qualifies for a Basic ACDP because the emissions will be more than 1 ton/year VOC and/or HAP and less than 5 tons/yr PM₁₀ in a PM₁₀ nonattainment or maintenance area, and less than 10 tons/yr. for each criteria pollutant emissions
4. The source is located in an attainment area for all pollutants except for PM₁₀. The Eugene Springfield Air Quality Maintenance Area is a nonattainment area for PM₁₀.
5. LRAPA has determined that sources that qualify for a Basic ACDP will not have significant emissions. In most cases the emission will not exceed 5 tons of PM or PM₁₀ or 10 tons of any other pollutant. Therefore, the Basic ACDP does not include Plant Site Emission Limits and it is not necessary to estimate emissions for each individual source.
6. Pursuant to LRAPA Section 37-0056(4), issuance of a new or renewed Basic Air Contaminant Discharge Permit requires public notice in accordance with LRAPA Section 31-0030(3)(a). Therefore, there will be no prior notice or public participation. However, LRAPA will maintain a list of all permit actions processed under Category I and make the list available for public review.

MTL
 3/11/2011