



LANE REGIONAL AIR PROTECTION AGENCY
1010 Main Street, Springfield, Oregon 97477
(541) 736-1056

SIMPLE AIR CONTAMINANT DISCHARGE PERMIT
(SIMPLE ACDP)

Issued in accordance with provisions of Title 37, Lane Regional Air Protection Agency's Rules and Regulations, and based on the land use compatibility findings included in the permit record.

Issued To:
Atkore Plastic Pipe Corporation
dba Ridgeline Pipe Manufacturing
2220 Nugget Way
Eugene, Oregon 97403

Information Relied Upon:
Application Number: 69469
Dated: March 6, 2023

Land Use Compatibility Statement:
From: City of Springfield
Date: December 16, 1999

Physical Location:
Same as above

Fee Basis:
Title 37, Table 1, Part B: 74
All Other Sources not listed herein that LRAPA determines an air quality concern exists or one which would emit significant malodorous emissions

Permit Number: 207488
Permit Type: Simple
SIC: 3084 – Plastic Pipe Extrusion
Date Renewed: November 28, 2022
Expiration Date: November 28, 2027
Modification Date: April 17, 2023

Permitted Sources:
Plastic Pipe Manufacturing

Emission Units:
Facility Wide PVC Pipe Extrusion including:
11 Process steps (Silos, Hoppers, and Blenders) with 26 Baghouses.
Seven Extrusion Lines

Issued By: Steven A. Dietrich
Steven A. Dietrich, Director

Effective Date: 4-17-23

Addendum No. 1
Non-PSD/NSR Simple Technical Permit Modification

In accordance with 37-0064(4)(b)(A) of LRAPA's Rules and Regulations, Simple Air Contaminant Discharge Permit No. 207488 is hereby amended to add a Shaker (EU12) and one (1) baghouse (BH26) to the Reground PVC process line. The cover page is amended to add the equipment, and to correct a mistake in the company name. Condition 2 is modified to include the Shaker and the baghouse. Condition 14 is modified to update the emission factor for Reground PVC by changing the BH passes from six (6) to seven (7). (All new language is in **bold**):

Emission Unit Description

2. The emission units (EUs) regulated by this permit are the following:

EU ID	Emission Unit (EU)	Control Device
EU1	Two (2) Calcium Carbonate Silos	BH23, BH24
EU2	Hoppers above blender	BH2, BH3, BH21, BH22
EU3	Four (4) Day Hoppers	BH9, BH10
EU4	Five (5) Compound Silos	BH6, BH7, BH8
EU5	Seven (7) Feed Hoppers	BH12, BH13, BH14, BH15, BH16, BH17, BH18
EU6	Regrind Bins	BH11
EU7	Recycle Feed Hopper	BH1
EU8	Recycle Silo	BH19
EU9	Recycle Hopper above blender	BH20
EU10	Saw Reclaim	BH25
EU11	Seven (7) Pipe Extrusion Lines	NA
EU12	Shaker	BH26

PSEL Monitoring

13. By the 15th day of each month, the permittee must demonstrate compliance with the PM, PM₁₀, and PM_{2.5} PSELs for the previous consecutive 12-month rolling period using the following equation: [LRAPA 34-016 and 42-0080]

$$E = \sum \left(\frac{P \times EF_a \times EF_b}{2000} \right)$$

- Where,
- E = The total emissions (tons) for a production throughput type.
 - ∑ = The symbol representing “summation of”.
 - P = The total production throughput or process parameter.
 - EF_a = The PM emission factor in pounds PM per pounds of throughput (see Condition 14).
 - EF_b = The emission factor for number of passes through baghouses (see Condition 14).
 - 2,000 = The number of pounds in a short ton.

14. The permittee must use the following emission factors for calculating the PM emissions required in Condition 13, unless alternative emission factors are approved by LRAPA. The permittee may request or LRAPA may require the use of alternative emission factors provided the emission factors are based on actual test data or other documentation (e.g., AP-42 compilation of emission

factors) that has been reviewed and approved by LRAPA. [LRAPA 34-016 and 42-0080]

Production Throughput	Pollutant	EF _a (lb/lb)	EF _b (BH Passes)
Imported Dry PVC resin	PM/PM ₁₀ /PM _{2.5}	2.0E-5	3
Calcium Carbonate	PM/PM ₁₀ /PM _{2.5}	2.0E-5	4
Purchased Recycle	PM/PM ₁₀ /PM _{2.5}	2.0E-5	4
Reground PVC	PM/PM ₁₀ /PM _{2.5}	2.0E-5	7

15. By the 15th day of each month, the permittee must demonstrate compliance with the VOC and HAP PSEs for the previous consecutive 12-month rolling period using the following equation: [LRAPA 34-016 and 42-0080]

$$E = \sum \left(\frac{P \times EF}{2000} \right)$$

- Where,
- E = The total emissions (tons) for a production throughput type.
 - ∑ = The symbol representing “summation of”.
 - P = The total production throughput or process parameter.
 - EF = The emission factor in (see Condition 16).
 - 2,000 = The number of pounds in a short ton.

16. The permittee must use the following emission factors for calculating the VOC and HAP emissions required in Condition 15, unless alternative emission factors are approved by LRAPA. The permittee may request or LRAPA may require the use of alternative emission factors provided the emission factors are based on actual test data or other documentation (e.g., AP-42 compilation of emission factors) that has been reviewed and approved by LRAPA. [LRAPA 34-016 and 42-0080]

Production Throughput	Pollutant	EF _a (lb/lb)
Imported Dry PVC resin	VOC/HAP	1.2E-5
Additives containing VOCs/HAPs	VOC/HAP	0.01



LANE REGIONAL AIR PROTECTION AGENCY
1010 Main Street, Springfield, Oregon 97477
(541) 736-1056

SIMPLE AIR CONTAMINANT DISCHARGE PERMIT
(SIMPLE ACDP)

Issued in accordance with provisions of Title 37, Lane Regional Air Protection Agency's Rules and Regulations, and based on the land use compatibility findings included in the permit record.

Issued To:

Atkore Plastic Pipe Company
dba Ridgeline Pipe Manufacturing
2220 Nugget Way
Eugene, Oregon 97403

Physical Location:

Same as above

Permit Number: 207488

Permit Type: Simple

SIC: 3084 – Plastic Pipe Extrusion

Date Renewed: November 28, 2022

Expiration Date: November 28, 2027

Information Relied Upon:

Application Number: 66193

Dated: April 28, 2020

Land Use Compatibility Statement:

From: City of Springfield

Date: December 16, 1999

Fee Basis:

Title 37, Table 1, Part B: 74

All Other Sources not listed herein that LRAPA determines an air quality concern exists or one which would emit significant malodorous emissions

Permitted Sources:

Plastic Pipe Manufacturing

Emission Units:

Facility Wide PVC Pipe Extrusion including:

10 Process steps (Silos, Hoppers, and Blenders) with 25 Baghouses.

Seven Extrusion Lines

Issued

By: _____

Steven A. Dietrich

Steven A. Dietrich, Director

Effective

Date: _____

11-28-22

Permitted Activities

1. Until this permit expires or is revoked, the permittee is herewith allowed to discharge air contaminants only in accordance with the permit application and the requirements, limitations, and conditions contained in this permit. This specific listing of requirements, limitations, and conditions does not relieve the permittee from complying with all other rules of Lane Regional Air Protection Agency (LRAPA).

Emission Unit Description

2. The emission units (EUs) regulated by this permit are the following:

EU ID	Emission Unit (EU)	Control Device
EU1	Two (2) Calcium Carbonate Silos	BH23, BH24
EU2	Hoppers above blender	BH2, BH3, BH21, BH22
EU3	Four (4) Day Hoppers	BH9, BH10
EU4	Five (5) Compound Silos	BH6, BH7, BH8
EU5	Seven (7) Feed Hoppers	BH12, BH13, BH14, BH15, BH16, BH17, BH18
EU6	Regrind Bins	BH11
EU7	Recycle Feed Hopper	BH1
EU8	Recycle Silo	BH19
EU9	Recycle Hopper above blender	BH20
EU10	Saw Reclaim	BH25
EU11	Seven (7) Pipe Extrusion Lines	NA

General Emission Limits

3. The permittee must ensure that particulate matter emissions from any air contaminant source installed, constructed, or modified on or after June 1, 1970 but prior to April 16, 2015, other than fuel burning equipment and fugitive emissions, do not exceed 0.14 grains per dry standard cubic foot (dscf). [LRAPA 32-015(2)(b)(B)]
4. The permittee must ensure that particulate matter emissions from any air contaminant source installed, constructed, or modified after April 16, 2015, other than fuel burning equipment and fugitive emissions, do not exceed 0.10 grains per dry standard cubic foot (dscf). [LRAPA 32-015(2)(c)]
5. The permittee must ensure that particulate matter emissions from any fuel burning equipment installed, constructed, or modified on or after June 1, 1970 but prior to April 16, 2015, must not exceed 0.14 grains per dry standard cubic foot (dscf) corrected to 12% CO₂ or 50% excess air. [LRAPA 32-030(1) and (3)]

6. The permittee must ensure that particulate matter emissions from any fuel burning equipment installed, constructed, or modified after April 16, 2015, must not exceed 0.10 grains per dry standard cubic foot (dscf) corrected to 12% CO₂ or 50% excess air. [LRAPA 32-030(2) and (3)]
7. The permittee must ensure that emissions from any air contaminant source, other than fuel burning equipment and fugitive emission sources, do not equal or exceed 20% opacity for a period or periods aggregating more than three (3) minutes in any one (1) hour. [LRAPA 32-010(3)]
8. The permittee must take reasonable precautions to prevent fugitive dust emissions from leaving the property of a source for a period or periods totaling more than 18 seconds in a six-minute period. Fugitive emissions must be measured by EPA method 22 with the minimum observation time of at least six minutes. Reasonable precautions include, but are not limited to the following: [LRAPA 48-015 (1) and (3)]
 - a. Using, where possible, water or chemicals for control of dust in the demolition of existing buildings or structures, construction operations, the grading of roads or the clearing of land;
 - b. Applying water or other suitable chemicals on unpaved roads, materials stockpiles, and other surfaces which can create airborne dusts;
 - c. Storing, transporting, and waste removal of material collected from air pollution control equipment using methods that prevent the material from becoming airborne, such as: covering or fully enclosing waste containers, and wetting down the material before it is dumped for waste removal, or other methods that are equally effective in preventing the material from becoming airborne;
 - d. Operating all contaminant generating processes so that fugitive type dust associated with the operation will be adequately controlled at all times;
9. The permittee must at all times maintain and operate all air contaminant generating processes and all control equipment in a manner which minimize air contaminant discharges in accordance with LRAPA's highest and best requirements. [LRAPA 32-005]
10. The permittee must perform routine maintenance of the baghouses and keep the following records. [LRAPA 34-016(1)]
 - a. Date the maintenance occurred.
 - b. Person(s) or organization performing the maintenance.
 - c. Description of the maintenance performed.

Plant Site Emission Limits (PSELs)

11. Total emissions from all sources located at the plant must not exceed the PSELs below. The PSELs apply to any 12 consecutive calendar month period. [LRAPA 42-0040, 42-0060]

Annual Plant Site Emission Limits (PSELS)
 (tons per year)

Pollutant	Plant Site Emission Limit (tons/year)
PM	24
PM ₁₀	14
PM _{2.5}	9
VOC	39
Individual HAP	9
Combined HAPs	24

12. Any changes in operation that may increase the emissions above the PSELS must be approved by LRAPA. Failure to do so may result in enforcement actions being taken by LRAPA. [LRAPA 37-0020]

PSEL Monitoring

13. By the 15th day of each month, the permittee must demonstrate compliance with the PM, PM₁₀, and PM_{2.5} PSELS for the previous consecutive 12-month rolling period using the following equation: [LRAPA 34-016 and 42-0080]

$$E = \sum \left(\frac{P \times EF_a \times EF_b}{2000} \right)$$

- Where,
- E = The total emissions (tons) for a production throughput type.
 - Σ = The symbol representing "summation of".
 - P = The total production throughput or process parameter.
 - EF_a = The PM emission factor in pounds PM per pounds of throughput (see Condition 14).
 - EF_b = The emission factor for number of passes through baghouses (see Condition 14).
 - 2,000 = The number of pounds in a short ton.

14. The permittee must use the following emission factors for calculating the PM emissions required in Condition 13, unless alternative emission factors are approved by LRAPA. The permittee may request or LRAPA may require the use of alternative emission factors provided the emission factors are based on actual test data or other documentation (e.g., AP-42 compilation of emission factors) that has been reviewed and approved by LRAPA. [LRAPA 34-016 and 42-0080]

Production Throughput	Pollutant	EF _a (lb/lb)	EF _b (BH Passes)
Imported Dry PVC resin	PM/PM ₁₀ /PM _{2.5}	2.0E-5	3
Calcium Carbonate	PM/PM ₁₀ /PM _{2.5}	2.0E-5	4
Purchased Recycle	PM/PM ₁₀ /PM _{2.5}	2.0E-5	4
Reground PVC	PM/PM ₁₀ /PM _{2.5}	2.0E-5	6

15. By the 15th day of each month, the permittee must demonstrate compliance with the VOC and HAP PSEs for the previous consecutive 12-month rolling period using the following equation: [LRAPA 34-016 and 42-0080]

$$E = \sum \left(\frac{P \times EF}{2000} \right)$$

- Where,
- E = The total emissions (tons) for a production throughput type.
 - Σ = The symbol representing "summation of".
 - P = The total production throughput or process parameter.
 - EF = The emission factor in (see Condition 16).
 - 2,000 = The number of pounds in a short ton.

16. The permittee must use the following emission factors for calculating the VOC and HAP emissions required in Condition 15, unless alternative emission factors are approved by LRAPA. The permittee may request or LRAPA may require the use of alternative emission factors provided the emission factors are based on actual test data or other documentation (e.g., AP-42 compilation of emission factors) that has been reviewed and approved by LRAPA. [LRAPA 34-016 and 42-0080]

Production Throughput	Pollutant	EF _a (lb/lb)
Imported Dry PVC resin	VOC/HAP	1.2E-5
Additives containing VOCs/HAPs	VOC/HAP	0.01

Recordkeeping Requirements

17. A record of the following data must be maintained for a period of at least **five (5) years** at the plant site and must be available for inspection by authorized representatives of LRAPA: [LRAPA 34-016(5)]

Facility-Wide Activity	Parameter	Units	Minimum Recording Frequency
Imported Dry PVC resin	Material Usage	Pounds	Monthly
Calcium Carbonate	Material Usage	Pounds	Monthly
Recycled Material (Purchased and Re grind)	Material Usage	Pounds	Monthly
Wax	Material Usage	Pounds	Monthly
Additives (such as Impact Modifiers)	Material Usage	Pounds	Monthly
Ink and Flush	Material Usage	Pounds	Monthly
Baghouse maintenance performed	Occurrence	NA	Occurrence

SUBMITTALS

Annual Fee

18. In accordance with adopted regulations, the permittee will be invoiced by **October 1st** each year with fees due on **December 1st** of each year. [LRAPA 37-8020 Table 2].

Reporting Requirements

19. **By February 15th of each year**, the permittee must submit an annual report to LRAPA. The report must contain the following information for the previous calendar year: [LRAPA 34-016 and 42-0080]
- a. Calculations of the PM, PM₁₀, PM_{2.5}, VOC and HAP emissions according to Conditions 13 through 16.
 - b. Material usage and/or throughput amounts according to Condition 17.
 - c. A summary of maintenance performed on pollution control equipment according to Condition 10.
 - d. A summary of complaints related to air quality received by the permittee during the previous calendar year and their resolution.
 - e. A summary of any upsets that resulted in planned and/or unplanned excess emissions as required by Condition G13.
 - f. Any changes that increase or decrease the number of times a process line goes through a baghouse.
 - g. A summary of additives used in the previous calendar year that contain VOCs and/or HAPs, and any new documentation (Environmental Data Sheets, Certified Product Data Sheets, etc.) showing the amounts of VOCs/HAPs contained, as applicable.

ALL INQUIRIES REGARDING THIS PERMIT SHOULD BE DIRECTED TO:

Lane Regional Air Protection Agency
1010 Main Street
Springfield, Oregon 97477
(541) 736-1056

CNC/rr
11/28/22

Abbreviations, Acronyms and Definitions

ACDP	Air Contaminant Discharge Permit
ADT	Air dry ton (contains 10% water)
ASTM	American Society for Testing and Materials
AQMA	Air Quality Maintenance Area
BACT	Best Available Control Technology
BDT	Bone dry ton (all water removed), same as ODT
BER	Baseline Emission Rate
CAO	Cleaner Air Oregon
CFR	Code of Federal Regulations
CO	Carbon Monoxide
CO ₂ e	Carbon dioxide equivalent
DEQ	Oregon Department of Environmental Quality
dscf	Dry standard cubic foot
EPA	United States Environmental Protection Agency
EU	Emission Unit
FAAA	Federal Clean Air Act
ft ²	Square foot
GHG	Greenhouse gases
gr/dscf	Grains per dry standard cubic foot
HAP	Hazardous Air Pollutant as defined by LRAPA title 44
I&M	Inspection and maintenance
lb	Pound(s)
LRAPA	Lane Regional Air Protection Agency
MM	Million
MACT	Maximum Achievable Control Technology
MMBtu	Million British thermal units
N/A	Not applicable
NAICS	North American Industry Classification System
NESHAP	National Emissions Standards for Hazardous Air Pollutants
NO _x	Nitrogen oxides
NSPS	New Source Performance Standard
NSR	New Source Review
O ₂	Oxygen
OAR	Oregon Administrative Rules
ODT	Oven dried ton (all water removed), same as BDT
ORS	Oregon Revised Statutes
O&M	Operation and maintenance
PCD	Pollution control device
PM	Particulate matter
PM ₁₀	Particulate matter less than 10 microns in size
PM _{2.5}	Particulate matter less than 2.5 microns in size
ppm	Part per million
PSD	Prevention of Significant Deterioration
PSEL	Plant Site Emission Limit
PTE	Potential to Emit
scf	Standard cubic foot
SER	Significant Emission Rate
SIC	Standard Industrial Code
SIP	State Implementation Plan
SO ₂	Sulfur dioxide
TACT	Typically Achievable Control Technology
TBACT	Toxics Best Available Control Technology
Therm	Approximately equivalent to energy from burning 100 cubic feet of natural gas
VE	Visible emissions
VOC	Volatile organic compound
year	A period consisting of any 12- consecutive calendar months

GENERAL PERMIT CONDITIONS

General Conditions and Disclaimers

- G1. A copy of the permit application and this Air Contaminant Discharge Permit (ACDP) must be available on site for inspection upon request. [LRAPA 37-0020(3)]
- G2. The permittee must allow the Director or his/her authorized representatives access to the plant site and pertinent records at all reasonable times for the purpose of making inspections, surveys, collecting samples, obtaining data, reviewing and copying air contaminant discharge records and otherwise conducting necessary functions related to this permit in accordance with ORS 468.095. [LRAPA 13-020(1)(h)]
- G3. The issuance of this permit does not convey any property rights in either real or personal property, or any exclusive privileges, nor does it authorize any injury to private property or any invasion of personal rights, nor any infringement of federal, state, or local laws or regulations.

Performance Standards and Emission Limits

- G4. The permittee must not cause or permit the deposition of any particulate matter which is larger than 250 microns in size at sufficient duration and quantity, as to create an observable deposition upon the real property of another person. [LRAPA 32-055]
- G5. The permittee must not discharge from any source whatsoever such quantities of air contamination which cause injury or damage to any persons, the public, business or property. Such determination to be made by LRAPA. [LRAPA 32-090(1)]
- G6. The permittee must not cause or permit emission of water vapor if the water vapor causes or tends to cause detriment to the health, safety or welfare of any person or causes, or tends to cause damage to property or business. [LRAPA 32-090(2)]
- G7. The permittee must not willfully cause or permit the installation or use of any device or use of any means which, without resulting in a reduction in the total amount of air contaminants emitted, conceals emissions of air contaminants which would otherwise violate LRAPA rules. [LRAPA 32-050(1)]
- G8. The permittee must not cause or permit the installation or use of any device or use of any means designed to mask the emissions of an air contaminant which causes or tends to cause detriment to health, safety or welfare of any person. [LRAPA 32-050(2)]
- G9. The permittee must not allow any materials to be handled, transported, or stored; or a building, its appurtenances or road(s) to be used, constructed, altered, repaired, or demolished; or any equipment to be operated, without taking reasonable precautions to prevent particulate matter from being airborne. [LRAPA 48-015(1)]
- G10. The permittee may not cause or allow air contaminants from any source subject to regulation by LRAPA to cause nuisance. [LRAPA 49-010(1)]

Excess Emissions: General Policy

- G11. Emissions of air contaminants in excess of applicable standards or permit conditions are unauthorized and are subject to enforcement action, pursuant to LRAPA 36-010 and 36-030. These rules apply to any permittee operating a source which emits air contaminants in violation of any applicable air quality rule or permit condition, including but not limited to excess emissions

resulting from the breakdown of air pollution control devices or operating equipment, process upset, startup, shutdown, or scheduled maintenance. Sources that do not emit air contaminants in excess of any applicable rule or permit condition are not subject to the recordkeeping and reporting requirements in LRAPA title 36. Emissions in excess of applicable standards are not excess emissions if the standard is in an NSPS or NESHAP and the NSPS or NESHAP exempts startups, shutdowns and malfunctions as defined in the applicable NSPS or NESHAP. [LRAPA 36-001(1)]

Excess Emissions: Notification and Record-keeping

- G12. For all other excess emissions not addressed in LRAPA Sections 36-010, 36-015, or 36-040, the following requirements apply: [LRAPA 36-020(1)]
- a. The owner or operator, of a small source, as defined by LRAPA 36-005(7), need not notify LRAPA of excess emissions events immediately unless otherwise required by permit condition, written notice by LRAPA, or if the excess emission is of a nature that could endanger public health.
 - b. Notification must be made to the LRAPA office. The current LRAPA telephone number during regular business hours (8 a.m. - 5 p.m., M-F) is (541) 736-1056. During nonbusiness hours, weekends, or holidays, the permittee must immediately notify LRAPA by calling the LRAPA Upset/Complaint Line. The current number is (541) 726-1930.
 - c. Follow-up reporting, if required by LRAPA, must contain all information required by Condition G15.
- G13. At each annual reporting period specified in this permit, or sooner if required by LRAPA, the permittee must submit a copy of the upset log entries for the reporting period, as required by Condition G15. [LRAPA 36-025(4)(a)]
- G14. Any excess emissions which could endanger public health or safety must immediately be reported to the Oregon Emergency Response System (OERS) at 1-800-452-0311.
- G15. The permittee must keep an upset log of all planned and unplanned excess emissions. The upset log must include the following: [LRAPA 36-025(3) and 36-030(1)]
- a. date and time each event was reported to LRAPA;
 - b. whether the process handling equipment and the air pollution control equipment were at all times maintained and operated in a manner consistent with good practice for minimizing emissions;
 - c. whether repairs or corrections were made in an expeditious manner when the permittee knew or should have known that emission limits were being or were likely to be exceeded;
 - d. whether the event was one in a recurring pattern of incidents which indicate inadequate design, operation, or maintenance; and
 - e. final resolution of the cause of the excess emissions.

Upset logs must be kept by the permittee for five (5) calendar years. [LRAPA 36-025(3)]

Excess Emissions: Scheduled Maintenance

- G16. If the permittee anticipates that scheduled maintenance of air contaminant sources or air pollution control devices may result in excess emissions, the permittee must obtain prior LRAPA

authorization of procedures that will be used to minimize excess emissions. Application for approval of procedures associated with the scheduled maintenance must be submitted and received by LRAPA in writing at least seventy-two (72) hours prior to the event. The application must include the following: [LRAPA 36-015(1)]

- a. reasons explaining the need for maintenance, including but not limited to: why the maintenance activity is necessary; why it would be impractical to shut down the source operation during the maintenance activity; if applicable, why air pollution control devices must be by-passed or operated at reduced efficiency during the maintenance activity; and why the excess emissions could not be avoided through better scheduling for maintenance or through better operation and maintenance practices;
- b. identification of the specific production or emission control device or system to be maintained;
- c. identification of the nature of the air contaminants likely to be emitted during the maintenance period, and the estimated amount and duration of the excess emissions, including measures such as the use of overtime labor and contract services and equipment that will be taken to minimize the length of the maintenance period; and
- d. identification of specific procedures to be followed which will minimize excess emissions at all times during the scheduled maintenance.

G17. No scheduled maintenance associated with the approved procedures in Condition G16 that is likely to result in excess emissions may occur during any period in which an Air Pollution Alert, Air Pollution Warning, or Air Pollution Emergency has been declared, or during an announced yellow or red woodstove advisory period, in areas determined by LRAPA as PM_{2.5} or PM₁₀ nonattainment areas. [LRAPA 36-015(6)]

G18. In cases where LRAPA has not received notification of scheduled maintenance that is likely to cause excess emissions within the required seventy-two (72) hours prior to the event, or where such approval has not been waived pursuant to LRAPA 36-015(3), the permittee must immediately notify LRAPA by telephone of the situation, and must be subject to the requirements of Conditions G12 and G13. [LRAPA 36-015(7)]

Air Pollution Emergencies

G19. The permittee must, upon declaration of an air pollution alert, air pollution warning, or air pollution emergency, take all emission reduction measures specified in Tables 1, 2, and 3 of LRAPA Title 51. Permittees responsible for a source of air contamination within a Priority I AQCR must, upon declaration of an episode condition affecting the locality of the air contamination source, take all appropriate actions specified in the applicable table and must take all appropriate actions specified in an LRAPA-approved preplanned abatement strategy for such condition which has been submitted and is on file with LRAPA. [LRAPA 51-015]

Notification of Construction/Modification

G20. The permittee must notify LRAPA in writing using an LRAPA "Notice of Intent to Construct" form, or other permit application forms and obtain approval in accordance with LRAPA 34-010 and 34-034 through 34-038 before:

- a. constructing, installing or establishing a new stationary source that will cause an increase in regulated pollutant emissions
- b. making any physical change or change in the operation of an existing stationary source that

- will cause an increase, on an hourly basis at full production, in any regulated pollutant emissions; or
- c. constructing or modifying any pollution control equipment.

Notification of Name Change

G21. The permittee must notify LRAPA in writing, using an LRAPA Application for Administrative Amendment to ACDP form, within 60 days after legal change of the registered name of the company with the Corporation Division of the State of Oregon. [LRAPA 37-0030(4)]

Applicable administrative fees must be submitted with an application for the name change.

Permit Renewal

G22. Application for renewal of this permit must be submitted not less than 120 days prior to the permit expiration date for Simple ACDPs, and 180 days prior to the permit expiration date for Standard ACDPs. [LRAPA 37-0040(2)(b)]

G23. A source may not be operated after the expiration date of a permit, unless any of the following occur prior to the expiration date of the permit: [LRAPA 37-0082(1)(a)]

- a. A timely and complete application for renewal or for an LRAPA Title V Operating Permit has been submitted; or
- b. Another type of permit, ACDP or Title V, has been issued authorizing operation of the source.

G24. For a source operating under an ACDP or LRAPA Title V Operating Permit, a requirement established in an earlier ACDP remains in effect notwithstanding expiration of the ACDP, unless the provision expires by its terms or unless the provision is modified or terminated according to the procedures used to establish the requirement initially. [LRAPA 37-0082(1)(c)]

G25. Any permittee who fails to submit any relevant facts or who has submitted incorrect information in a permit application must, upon becoming aware of such failure or incorrect submittal, promptly submit such supplementary facts or corrected information. [LRAPA 37-0040(4)]

Termination Conditions

G26. This permit will be automatically terminated upon: [LRAPA 37-0082(2)]

- a. Issuance of a renewal or new ACDP for the same activity or operation;
- b. Written request of the permittee, if LRAPA determines that a permit is no longer required;
- c. Failure to submit a timely application for permit renewal. Termination is effective on the permit expiration date; or;
- d. Failure to pay annual fees within 90 days of invoice by LRAPA, unless prior arrangements for payment have been approved in writing by LRAPA.

G27. If LRAPA determines that a permittee is in noncompliance with the terms of the permit, submitted false information in the application or other required documentation, or is in violation of any applicable rule or statute, LRAPA may revoke the permit. LRAPA will provide notice of the intent to revoke the permit to the permittee under LRAPA title 31. The notice will include the reasons why the permit will be revoked, and include an opportunity for the permittee to request a

contested case hearing prior to the revocation. A written request for hearing must be received by LRAPA within 60 days from service of the notice on the permittee, and must state the grounds of the request. The hearing will be conducted as a contested case hearing under ORS 183.413 through 183.470 and LRAPA title 14. The permit will continue in effect until the 60th day after service of the notice on the permittee, if the permittee does not timely request a hearing, or until a final order is issued if the permittee timely requests a hearing. [LRAPA 37-0082(4)(a)]

- G28. A permit automatically terminated under LRAPA 37-0082(2)(b) through (2)(d) may only be reinstated by the permittee by applying for a new permit. The permittee must also pay the applicable new source permit application fees in this title unless the owner or operator submits the renewal application within three months of the permit expiration date. [LRAPA 37-0082(3)]
- G29. If LRAPA finds there is a serious danger to the public health, safety or the environment caused by a permittee's activities, LRAPA may immediately revoke or refuse to renew the permit without prior notice or opportunity for a hearing. If no advance notice is provided, notification will be provided to the permittee as soon as possible as provided under LRAPA Title 31. The notification will set forth the specific reasons for the revocation or refusal to renew and will provide an opportunity for the permittee to request a contested case hearing for review of the revocation or refusal to renew. A permittee's written request for hearing must be received by LRAPA within 90 days of service of the notice on the permittee and must state the grounds for the request. The hearing will be conducted as a contested case hearing under ORS 183.413 through 183.470 and LRAPA Title 14. The revocation or refusal to renew becomes final without further action by LRAPA if a request for a hearing is not received within the 90 days. If a request for a hearing is timely received, the revocation or refusal to renew will remain in place until issuance of a final order. [LRAPA 37-0082(4)(b)]
- G30. Any hearing requested must be conducted pursuant to the rules of LRAPA. [LRAPA title 14]

Asbestos

- G31. The permittee must comply with the asbestos abatement requirements in LRAPA title 43 for all activities involving asbestos-containing materials, including, but not limit to, demolition, renovation, repair, construction, and maintenance. [LRAPA title 43]

[Revised 1/12/2018]