

Page 1 of 8 Pages

# BASIC AIR CONTAMINANT DISCHARGE PERMIT

Lane Regional Air Protection Agency 1010 Main Street Springfield, OR 97477 Telephone: (541) 736-1056

This permit is being issued in accordance with the provisions of LRAPA's Rules and Regulations and based on the land use compatibility findings included in the permit record.

ISSUED TO:	INFORMATION RELIED UPON:

Fuller Cabinets, Inc. Application No.: 69285

91 S. Danebo Avenue Date Received: February 9, 2023 Eugene, OR 97402

PLANT SITE LOCATION: LAND USE COMPATIBILITY

STATEMENT:

91 S. Danebo Avenue
Eugene, OR 97402
Approving Authority:

Approving Authority: City of Eugene Approval Date: January 27, 2016

## ISSUED BY THE LANE REGIONAL AIR PROTECTION AGENCY

Steven a. Vietrich	5-12-23		
Steven A. Dietrich, Director	Dated		

Source(s) Permitted to Discharge Air Contaminants (LRAPA Title 37, Section 37-0020):

Table 1 Code	Source Description	SIC
Part A.7	Surface coating operations whose actual or expected usage of coating materials is greater than 250 gallons per year, but less than 250 gallons per month, excluding sources that exclusively use non-VOC and non-HAP containing coatings.	2541

Page 2 of 8 Pages

#### 1.0 PERMIT ISSUANCE

# 1.1 Permitted Activities

The permittee is allowed to discharge air contaminants from processes and activities related to the air contaminant source(s) listed on the first page of this permit until this permit expires, is modified, revoked or rescinded, as long as the permittee complies with the conditions of this permit. If there are other emissions activities occurring at the site besides those listed on the cover page of this permit, the permittee may be required to obtain a General, Simple or Standard ACDP, if applicable.

#### 2.0 GENERAL EMISSION STANDARDS AND LIMITS

# 2.1 Production Limits

The permittee is prohibited from using 250 gallons or more of any VOC-containing coating materials in a calendar month without first notifying LRAPA.

The permittee is prohibited from producing more than 25,000 board feet of finished product per 8-hour input without first notifying LRAPA.

# 2.2 Visible Emissions

The permittee must comply with the following visible emission limits, as applicable:

- a. Visible emissions from any air contaminant source must not equal or exceed an average 20% opacity for a period or periods aggregating more than three minutes in any one hour. [LRAPA 32-010(3)]
- b. Observations must be recorded at 15-second intervals as specified in LRAPA 32-010(2).
- c. The visible emissions standard in this condition does not apply to fugitive emissions from the source. [LRAPA 32-010(1)]

# 2.3 Particulate Matter Emissions

Particulate matter emissions from any air contaminant source, other than fugitive emission sources, must not exceed:

- a. 0.14 grains per dry standard cubic foot for sources installed, constructed or modified prior to April 16, 2015; and [LRAPA 32-015(2)(b)]
- b. 0.10 grains per dry standard cubic foot for sources installed, constructed or modified after April 16, 2015. [LRAPA 32-015(2)(c)]

Page 3 of 8 Pages

2.4 Fugitive Emissions

The permittee must take reasonable precautions to prevent particulate matter from becoming airborne. [LRAPA 48-015]

2.5 Particulate Matter Fallout

The permittee must not cause or permit the emission of particulate matter larger than 250 microns in size at such duration or quantity, as to create an observable deposition upon the real property of another person.

[LRAPA 32-055]

2.6 Nuisance and Odors

The permittee must not cause or allow air contaminants from any source to cause a nuisance. Nuisance conditions will be verified by LRAPA personnel. [LRAPA 49-010]

## 3.0 OPERATION AND MAINTENANCE REQUIREMENTS

3.1 Operation of Pollution Control Devices and Processes

The permittee must operate and maintain air pollution control devices and emission reduction processes at the highest reasonable efficiency and effectiveness to minimize emissions. Air pollution control devices and components must be in operation and functioning properly at all times when the associated emission source is operating. Air pollution control devices include the following equipment: spray booth filters and baghouse that controls particulate matter from the cabinet manufacturing and finishing process. [LRAPA 32-007(1)]

## 4.0 RECORDKEEPING REQUIREMENTS

4.1 Monitoring Requirements

The permittee must monitor and maintain records of the operation and maintenance of the facility as required in Condition 5.2: [LRAPA 34-016(1)]

4.2 Operation and Maintenance

The permittee must maintain all records associated with operation and maintenance of the facility and associated air contaminant control devices, including, but not limited to, safety data sheets (SDS) or certified product data sheets (CPDS) for each coating material, calculations, production records, and maintenance records. [LRAPA 34-016(1)]

4.3 Excess Emissions

The permittee must maintain records of excess emissions as defined in LRAPA title 36 (recorded on occurrence). Typically, excess emissions are caused by process upsets, startups, shutdowns, or scheduled maintenance. Excess emissions are evident when visible emissions are greater than 20% opacity for a period or periods aggregating more than three minutes in any one hour. [LRAPA 36-025]

Page 4 of 8 Pages

## 4.4 Complaint log

The permittee must maintain a log of all written complaints and complaints received via telephone, fax, or email that specifically refer to air pollution concerns associated to the permitted facility. The log must include a record of the permittee's actions to investigate the validity of each complaint and a record of actions taken for complaint resolution. [LRAPA 34-016(1)]

# 4.5 Retention of Records

Unless otherwise specified, all records must be maintained on site for a period of at least five (5) years and must be made available to LRAPA upon request. [LRAPA 34-016(5)]

#### 5.0 REPORTING REQUIREMENTS

## 5.1 Excess Emissions

The permittee must notify LRAPA by telephone or in person of any excess emissions which are of a nature that could endanger public health. [LRAPA 36-020]

- a. Such notice must be provided as soon as possible, but never more than one hour after becoming aware of the problem. Notice must be made to the LRAPA office identified in Condition 6.2.
- b. If the excess emissions occur during non-business hours, the permittee must notify LRAPA by calling the Oregon Emergency Response System (OERS). The current number is 1-800-452-0311.
- c. The permittee must also submit follow-up reports when required by LRAPA.

#### 5.2 Annual Report

The permittee must submit to LRAPA by **February 15** of each year this permit is in effect, the following information for the preceding calendar year:
[LRAPA 34-016(2)]

- a. Operating parameters:
  - Annual number of gallons of VOC and/or HAP containing coatings and solvents used; and
  - ii. Maximum quantity of lumber (board feet) input in an 8-hour period; and
  - iii. Annual amount of lumber (board feet) produced.
- b. Records of all planned and unplanned excess emissions events.
- c. Summary of complaints relating to air quality received by the permittee.

Page 5 of 8 Pages

 d. List of permanent changes made in facility processes, production levels, and pollution control equipment which affected air contaminant emissions.

e. List of major maintenance performed on pollution control equipment.

# 5.3 Notice of Change of Ownership or Company Name

The permittee must notify LRAPA in writing using a LRAPA "Permit Application Form" within 60 days after the following: [LRAPA 37-0030(4)]

- Legal change of the name of the company as registered with the Corporation Division of the State of Oregon; or
- b. Sale or exchange of the activity or facility.

## 5.4 Construction or Modification Notices

The permittee must notify LRAPA in writing using a LRAPA "Notice of Construction Form," or "Permit Application Form," and obtain approval in accordance with LRAPA 34-010 through 34-038 before:

- a. Constructing, installing, or establishing a new source that will cause an increase in any regulated pollutant emissions; [LRAPA 34-034(1)]
- b. Making a physical change or change in operation of an existing source that will cause an increase, on an hourly basis at full production, in any regulated pollutant emissions; or [LRAPA 34-034(2)]
- c. Constructing or modifying any air pollution control device. [LRAPA 34-034(3)]

### 5.5 Where to Send Reports and Notices

The reports, with the permit number prominently displayed, must be sent to LRAPA as identified in Condition 6.2.

#### 6.0 ADMINISTRATIVE REQUIREMENTS

# 6.1 Renewal of the Basic Permit

A complete application for renewal of this permit is due within 30 days prior to expiration. [LRAPA 37-0040(2)(b)(A)]

- a. If LRAPA is delinquent in renewing the permit, the existing permit will remain in effect and the permittee must comply with the conditions of the permit until such time that the permit is renewed.
- b. The permittee may submit an application for either a General, Simple or Standard ACDP at any time, but the permittee must continue to comply with the Basic

Page 6 of 8 Pages

ACDP until LRAPA takes final action on the General. Simple or Standard ACDP application.

If a complete application for renewal of the Basic C. ACDP or a General, Simple or Standard ACDP application is filed with LRAPA in a timely manner, the permit will not be deemed to expire until final action has been taken on the application.

#### 6.2 **LRAPA Address** and Contact Number

All reports, notices, and applications should be directed to the LRAPA office. The LRAPA address is as follows:

Lane Regional Air Protection Agency

1010 Main Street Springfield, OR 97477

Telephone: (541) 736-1056

#### 6.3 **LRAPA** Website

Information about air quality permits and LRAPA's regulations may be obtained from the LRAPA web page at www.lrapa.org.

#### 7.0 **FEES**

#### 7.1 **Annual Fees**

The Annual Fees specified in LRAPA title 37, section 37-8020, Table 2, Parts 2 and 3 for a Basic ACDP are due on **December 1** of each year this permit is in effect. An invoice indicating the amount, as determined by LRAPA regulations, will be mailed prior to the above date. [LRAPA 37-0056(2)]

#### Where to Submit Fees must be submitted to: 7.2

Fees

Lane Regional Air Protection Agency 1010 Main Street

Springfield, OR 97477 Telephone: (541) 736-1056

#### **GENERAL CONDITIONS AND DISCLAIMERS** 8.0

8.1 Other Regulations In addition to the specific requirements listed in this permit, the permittee must comply with all other legal requirements enforceable by LRAPA.

#### Conflicting 8.2 Conditions

In any instance in which there is an apparent conflict relative to conditions in this permit, the most stringent conditions apply.

Permit Number: 205195 Expiration Date: May 12, 2033 Page 7 of 8 Pages

8.3	Masking of Emissions	The permittee must not cause or permit the installation of any device or use any means designed to mask the emissions of an air contaminant that causes or is likely to cause detriment to health, safety, or welfare of any person or otherwise violate any other regulation or requirement. [LRAPA 32-050]
8.4	LRAPA Access	The permittee must allow LRAPA's representatives access to the plant site and pertinent records at all reasonable times for the purposes of performing inspections, surveys, collecting samples, obtaining data, reviewing and copying air contaminant emissions discharge records and conducting all necessary functions related to this permit in accordance with ORS 468.095.
8.5	Permit Availability	The permittee must have a copy of the permit available at the facility at all times.
8.6	Outdoor Burning	The permittee may not conduct any outdoor burning except as allowed by LRAPA title 47.
8.7	Asbestos	The permittee must comply with the asbestos abatement requirements in LRAPA title 43 for all activities involving asbestos-containing materials, including, but not limit to, demolition, renovation, repair, construction, and maintenance.
8.8	Property Rights	The issuance of this permit does not convey any property rights in either real or personal property, or any exclusive privileges, nor does it authorize any injury to private property or any invasion of personal rights, nor any infringement of federal, state, or local laws or regulations.
8.9	Termination, Revocation, or Modification	LRAPA may terminate, modify or revoke this permit in accordance with LRAPA title 37, section 37-0082 and section 37-0084.

Permit Number: 205195 Expiration Date: May 12, 2033 Page 8 of 8 Pages

## 9.0 ABBREVIATIONS, ACRONYMS, AND DEFINITIONS

ACDP	Air Contaminant Discharge	NSR	New Source Review
	Permit	$O_2$	Oxygen
ASTM	American Society for Testing	OAR	Oregon Administrative Rules
	and Materials	ORS	Oregon Revised Statutes
AQMA	Air Quality Maintenance Area	O&M	Operation and maintenance
calendar	The 12-month period	Pb	Lead
year	beginning January 1st and	PCD	Pollution control device
	ending December 31st	PM	Particulate matter
CFR	Code of Federal Regulations	PM <sub>10</sub>	Particulate matter less than
CO	Carbon monoxide		10 microns in size
DEQ	Oregon Department of	ppm	Part per million
dscf	Environmental Quality  Dry standard cubic foot	PSD	Prevention of Significant Deterioration
EPA	US Environmental Protection	PSEL	Plant Site Emission Limit
EPA	Agency	PTE	Potential to Emit
FCAA	Federal Clean Air Act	RACT	Reasonably Available
gal	Gallon(s)		Control Technology
gr/dscf	Grains per dry standard	scf	Standard cubic foot
J	cubic foot	SER	Significant Emission Rate
HAP	Hazardous Air Pollutant as	SIC	Standard Industrial Code
	defined by LRAPA title 44	SIP	State Implementation Plan
ID	Identification number	SO <sub>2</sub>	Sulfur dioxide
I&M	Inspection and maintenance	Special	As defined in LRAPA title 29
lb	Pound(s)	Control	
MMBtu	Million British thermal units	Area	
NA	Not applicable	VE	Visible emissions
NESHAP	National Emissions	VOC	Volatile organic compound
	Standards for Hazardous Air Pollutants	year	A period consisting of any 12-consecutive calendar
$NO_X$	Nitrogen oxides		months
NSPS	New Source Performance		

CG:rr 5/11/2023

Standard



Permit No.: 205195 Application No.: 69285

Expiration Date: May 12, 2033

Page 1 of 2

#### Lane Regional Air Protection Agency

## BASIC AIR CONTAMINANT DISCHARGE PERMIT REVIEW REPORT

Fuller Cabinets, Inc. 91 S. Danebo Avenue Eugene, Oregon 97402 541-349-9887

Website: https://www.fullcab.com/

Reports					
Annual	Semi-annual	Excess Emissions	NSPS	NESHAP	Public Notice
Feb 15	NA	X	NA	NA	Category I

- The proposed permit is a renewal of an existing Basic Air Contaminant Discharge Permit (ACDP) issued to Fuller Cabinets (the facility) located at 91 S. Danebo Avenue in Eugene, Oregon. The facility's initial permit (existing permit) was issued on May 10, 2013. Two separate addendums to the existing permit were issued on February 18, 2016, and January 24, 2019, to update the facility address and company name, respectively, to current.
- 2. The permittee owns and operates a cabinet and similar product manufacturing facility. The facility uses approximately 54 gallons per month of VOC- and HAP-containing coatings per month. The facility currently operates two (2) paint booths with filters for surface coating operations and one (1) baghouse to control particulate matter emissions from sawing, sanding, planing, and routing wood. The facility also operates one (1) edge banding machine to apply laminate edges to wood panels.
- 3. Board feet production levels are currently less than 5,000 board feet per maximum 8-hour period, therefore, the source category for millwork in LRAPA title 37, Table 1 (category A.9) is not applicable to the facility. However, the facility conducts surface coating operations consistent with source category A.7 and qualifies for a Basic ACDP because the expected usage of VOC- and HAP-containing coating materials used in the surface coating operation is greater than 250 gallons per year, but less than 250 gallons per month.
- 4. The source is located in an attainment area for PM<sub>2.5</sub>, SO<sub>2</sub>, NO<sub>2</sub>, VOC (ozone), and Lead (Pb), and in the Eugene Springfield Air Quality Maintenance Area for PM<sub>10</sub> and CO.

Permit No.: 205195 Application No.: 69285

Expiration Date: May 12, 2033

Page 2 of 2

5. LRAPA has determined that sources that qualify for a Basic ACDP will not have significant emissions. In most cases the emission will not exceed 5 tons of PM or PM<sub>10</sub> or 10 tons of any other pollutant. Therefore, the Basic ACDP does not include Plant Site Emission Limits and it is not necessary to estimate emissions for each individual source.

6. Pursuant to subsection 37-0056(4), issuance of a new or renewed Basic Air Contaminant Discharge Permit requires public notice in accordance with paragraph 31-0030(3)(a). Therefore, there will be no prior notice or public participation. However, LRAPA will maintain a list of all permit actions processed under Category I and make the list available for public review.

CG:rr 5/11/2023