



LRAPA
Lane Regional Air Protection Agency

Phone (541) 736-1056 Fax (541) 726-1205 1-877-285-7272 http://www.lrapa.org E-mail: lrapa@lrapa.org

Certified Mail#91 7199 9991 7036 7647 7526

December 2, 2019

Todd Payne Manager Seneca Sustainable Energy, LLC P.O. Box 851 Eugene, OR 97402

Re: Cleaner Air Oregon (CAO) Call-in

Mr. Payne:

This letter provides written notice to you in accordance with OAR 340-245-0050 that Seneca Sustainable Energy, LLC, LRAPA Source Number 206470, has been called in to the Cleaner Air Oregon program.

Governor Kate Brown initiated the Cleaner Air Oregon program in 2016. The goal of CAO is to better understand emissions of toxic air contaminants and evaluate potential health risks to people near commercial and industrial facilities that emit regulated toxic air contaminants, communicate those results to affected communities, and if needed, reduce those risks to below health-based standards.

Your facility identified above must perform a risk assessment in accordance with the rules adopted by the Environmental Quality Commission (EQC). LRAPA is provided authority by the EQC to implement the CAO program in OAR 340-245-0010(3). This assessment will require you to provide information about current and potential emissions (e.g., production activities, emissions units, and control devices). This information will be used in conjunction with other data about where your facility is located to estimate risks to the surrounding community as required under Oregon Administrative Rules (OAR) 340-245-0050(1)(a):

- (a) When notified in writing by [LRAPA], at [LRAPA's] discretion, the owner or operator of an existing source with an operating permit must either demonstrate that it is an exempt source or:
- (A) Assess risk from the source using any of the Level 1 through Level 4 Risk Assessment procedures in sections (8) through (11);
- (B) Assess risk from the source using the emissions inventory submitted under OAR 340-245-0040(1); and
- (C) Follow the applicable calculation procedures under OAR 340-245-0200.

## Next Steps:

- Submit the CAO Pre-Application Fee form (<u>AQ100CAO</u>) with payment of the Call-In Fee by January 2, 2020, as identified in <u>OAR 340-245-0400(3)</u>. The CAO Call-In fee associated with your Title V Permit is \$10,000.
- 2. Submit the CAO Emissions Inventory Form (<u>AQ405CAO</u>) by 5pm on March 2, 2020, as required under <u>OAR 340-245-0030(1)(a)</u>. For most facilities, this emissions inventory will be more detailed than the toxic air contaminant emissions inventory submitted in 2017 because it will include information about maximum daily emissions as well as annual average emissions. If you wish to complete additional testing, this may affect submittal deadlines.

LRAPA will need to be able to verify the information submitted in your Emissions Inventory. In order for LRAPA to be able to approve your submission, please be sure to provide all supporting documents, including emissions factors and calculation methods. LRAPA will consider submissions incomplete if submitted without supporting information.

With the exception of the LRAPA form (AQ100CAO) mentioned above, information about CAO permitting and a flow chart showing the risk assessment process can be found on the "Cleaner Air Oregon Risk Assessment Process and Forms" tab at <a href="https://www.oregon.gov/deq/aq/aqPermits/Pages/CAO-reg.aspx">https://www.oregon.gov/deq/aq/aqPermits/Pages/CAO-reg.aspx</a>.

LRAPA is available for consultation prior to reviewing and approving information submittals for the CAO permitting process, including the Emissions Inventory, Modeling Protocol, Risk Assessment Work Plan (if you plan to complete a Level 3 or Level 4 risk assessment) and the Risk Assessment itself. Once the risk assessment is complete and approved, the Risk Action Levels in OAR 340-245-8010 determine whether additional action is required.

Your contact for CAO risk assessment work is: Jonathan Wright, Environmental Engineer 541-736-1056 ext. 236
Jonathan@lrapa.org

Please contact LRAPA to clarify any questions you may have regarding the emissions inventory and risk assessment process. We look forward to working with you.

Sincerely,

Max Hueftle, P.E., BCEE

Permit Section Manager (541) 736-1056, ext. 231 Email: max@lrapa.org

Cc: Merlyn Hough, LRAPA Director

File





1010 Main Street Springfield, OR 97477



CERTIFIED MAIL

02 1P \$ 006.800 0000827956 DEC 02 2019 MAILED FROM ZIP CODE 97477

Todd Payne, Manager Seneca Sustainable Energy, LLC P.O. Box 851 Eugene, OR 97402

PS Form 3811, July 2015 PSN 7530-02-000-9053	2. Article Number (Transfer from service label)	5 39	Eugene, OR 97402	Todd Payne, Manager CAO Ltr Seneca Sustainable Energy, LLC P.O. Box 851	1. Article Addressed to:	<ul> <li>Attach this card to the back of the malipiece, or on the front if space permits.</li> </ul>	<ul> <li>Complete items 1, 2, and 3.</li> <li>Print your name and address on the reverse</li> </ul>	SENDER: COMPLETE THIS SECTION	
Domestic Return Receipt	☐ Signature Confirmation ☐ Insured Mail Restricted Delivery Restricted Delivery (over \$500)	3. Service Type  Adult Signature Restricted Delivery  Adult Signature Restricted Delivery  Certified Mail Restricted Delivery  Certified Mail Restricted Delivery  Collect on			D. Is delivery address different from Item 1? L1 Yes If YES, enter delivery address below:   \[ \square\$ No	B. Received by (Printed Name)  C. Date of Delivery	A. Signature	COMPLETE THIS SECTION ON DELIVERY	The state of the s

PRINTED ON RECYCLED PAPER.

1